

cc: John E. Manley

Anchorage, Alaska  
February 11, 1960

File: 581

To: MacMaster, Edward  
MacMaster, Anchorage

From: Acting Superintendent of Operations

Subject: Derailment January 31 in Seward Road  
101-55

Reference derailment of Union 577 North of January 31, 1960,  
at switch on Roundhouse Road in Seward Road.

Inspection of scene of accident by Engineering Department  
shows that this switch was previously run through.

You are to contact all crews on this matter and advise them  
to the effect that if any switch is run through and not reported severe  
disciplinary action will be taken with crew involved.

Loy T. Boyd

WJB

cc: John E. Hanley

Anchorage, Alaska  
February 6, 1958

File: 581

To: Trainmasters, Anchorage

From: Acting Superintendent of Operations

Subject: AX-20

Reference Accident Report Number 20 covering derailment at corner  
of tracks 557 North January 31.

Conductor Nichols states as cause 'Cars jumped at Roundhouse Switch.'  
This is not a statement as to what caused this derailment. On his investi-  
gation at the scene of the accident he should have ascertained if possible  
the probable cause of this accident.

Please contact Conductor Nichols and advise this office your findings.

Lloyd V. Loyd