

INSPECTION REPORT

Inspector's Name King, Brandon		Inspector's Signature			Inspector's ID No. 48373	Report No. 55	Date yy mm dd 2020 08 17						
Railroad/Company Name & Address ALASKA RR CORP. 521 Ocean Dock Rd Anchorage AK 99501				R/C R RR/Co. Code ARR	Division SYSTEM Subdivision SYSTEM	RR/Co. Representative (Receipt Acknowledged) Name Sean Meloh Title Chief Mechanical Officer Email meslohs@akrr.com Signature _____							
From: City WASILLA	Codes 2790	Destination City & County			Codes	From Latitude							
State AK	02	City				From Longitude							
County MATANUSKA SUSITNA	C170	County				To Latitude							
Mile Post: From	To	Inspection Point BOILER 557 RESTORATION PROGRESS INSPECTION				To Longitude							
Activity Code:	230												
Units:	1												
Sub Units:	0												
Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
1	ARR	557	STM							N	N	0	
Description - [** Comment to Railroad/Company **] Conducted unannounced site visit and progress inspection of Steam Locomotive #557 at the Wasilla engine house. The condition of 557 and the quality of repairs appear to be of exceptional quality and the attention to detail is outstanding. At the time of my inspection the firebox sheets were complete and installed, NO tubes were installed and the discussion of future progress and specific milestones as the tube installation and its importance in the 15 year or 1,472 service day life of the boiler was discussed.													
Seal Applied			Seal Removed			Hazard Class			UN/NA ID				
Violation Recommended				<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		Latitude:			Longitude:				
Written Notification to FRA of Remedial Action is:				<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional		Railroad Action Code		Date(mm/dd/yyyy):		Comments on back?			